



Department of Energy

Ohio Field Office

Fernald Area Office

P. O. Box 538705

Cincinnati, Ohio 45253-8705

(513) 648-3155



2478

AUG 24 1999

Mr. James A. Saric, Remedial Project Manager
U.S. Environmental Protection Agency
Region V-SRF-5J
77 West Jackson Boulevard
Chicago, Illinois 60604-3590

DOE-1056-99

Mr. Tom Schneider, Project Manager
Ohio Environmental Protection Agency
401 East 5th Street
Dayton, Ohio 45402-2911

Dear Mr. Saric and Mr. Schneider:

TRANSMITTAL OF COLOR COPIES OF THE 1998 INTEGRATED SITE ENVIRONMENTAL REPORT

Reference: Letter, J. Reising to J. Saric and T. Schneider, "Transmittal of the 1998 Integrated Site Environmental Report," dated May 28, 1999 (DOE-0794-99)

This letter transmits color copies of the Fernald Environmental Management Project's (FEMP) 1998 Integrated Site Environmental Report. The color copies of the summary report are intended to replace the black and white reproduction copies previously transmitted to you (referenced letter).

It should be noted that a few corrections have been made to the color version of the summary report. These corrections mainly consist of the following:

- Minor grammatical corrections
- Corrections to the amount of water pumped from the extraction wells on Pages 43 and 51
- Corrections to three (water pumped) numbers in Table 3-1 (South Plume/South Plume Optimization Module number along with the total overall system and net number).

In addition to the water pumped numbers in Table 3-1, it should be noted that the total water pumped (1124.5 million gallons) and the net amount pumped (973.6 million gallons) should also be reflected in Table A.1-1 of Appendix A.1 to correctly agree with Table 3-1.

Mr. James A. Saric
Mr. Tom Schneider


-2-

AUG 24 1999

Because Table A.1-1 will not be updated, this clarification is being identified through this letter. Finally, text that was omitted from the black and white version on the first page of Chapter 4 has been reinserted.

Please contact Kathleen Nickel at (513) 648-3166 if you have any questions concerning this report.

Sincerely,



Johnny W. Reising
Fernald Remedial Action
Project Manager

FEMP:Nickel

Enclosure

cc w/enclosure:

N. Hallein, EM-42/CLOV (~~w/CD-ROM~~)

G. Jablonowski, USEPA-V, SRF-5J

J. Saric, USEPA-V, SRF-5J (~~w/CD-ROM~~)

T. Tucker, OEPA-Columbus

T. Schneider, OEPA-Dayton (~~three copies of enclosure w/CD-ROM~~)

F. Bell, ATSDR

M. Schupe, HSI GeoTrans (~~w/CD-ROM~~)

R. Vandegrift, ODH

F. Barker, Tetra Tech (~~w/CD-ROM~~)

AR Coordinator, FDF/78

cc w/o enclosure:

D. Carr, FDF/52-2

T. Hagen, FDF/65-2

J. Harmon, FDF/90

R. Heck, FDF/2

S. Hinnefeld, FDF/31

T. Walsh, FDF/65-2

ECDC, FDF/52-7

2